STATEMEI AND PLAN	of Health Care Fac NT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE A. BUILDING		(X3) DATE SURVEY COMPLETED 03/07/2018	
		TN7502	B WING	03/		
	PROVIDER OR SUPPLIER	1530 MI	ODRESS, CITY, S' DDLE TENNES EESBORO, TN	SEE BLVD		
(X4) ID PREFIX TAG	(FACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIEN	TION SHOULD BE THE APPROPRIATE	(X5 COMPL DAT
K 000	#43081, #43322 an 3/5/18 to 3/7/18 at B Rehabilitation and N were cited related to complaint investigate	and complaint investigation d #43654 were completed on Boulevard Terrace Nursing Home. No deficiencies to the licensure survey and tion #43081, #43322 and other 1200-8-6, Standards for	1 1			

STATE FORM

)

K5H011

If continuation sheet 1 of 1

ND PLAN	NT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 02 - BOULEVARD TERRAACE NURSING HOME		(X3) DATE SURVEY COMPLETED 03/05/2018	
		TN7502	B. WING_	The second secon	03/0	5/2018
IAME OF I	PROVIDER OR SUPPLIER			, STATE, ZIP CODE		
OULEV	ARD TERRACE REHA		DLE TENNI ESBORO, T			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLET DATE
	maintain the condition the overall nursing the overall nursing the manner that the safresidents are assured. This Rule is not me Based on observation maintain the physical environment. The findings include the condition of the outside B.3.1.2* (2012 Edition). Maintenance staff we deficiencies were idea.	shall construct, arrange, and on of the physical plant and nome environment in such a ety and well-being of the ed. It as evidenced by: on, the facility failed to al plant and overall d: 15/2018 at 12:45 AM, revealed atches (drywall fastened over joints fire caulked) in the boiler room. NFPA 101, n) NFPA 101, 8.3.4.1 (2012) as present when these entified and the administrator deficiencies during the exit	N 831	 N 831 The 5 drywall patches fastened of existing drywall with joints fire cauthe ceiling of the outside boiler romoved and replaced with proper board, tape and mud by the Plant Operations Manger (POM) on 3/8 An audit was done on 3/20/2018 Plant Operations Manager (POM) ensure the facility was in complian N831 by assessing all ceilings threfacility. No further discoveries were discoveries were discoveried with the Plant Operations Manager and Plant Operations Manager and Plant Operations Manager and Plant Operations Manager (POM) or detecting drywall repairs. Weekly audits will be done by the Operations Manager (POM) or detecting drywall repairs. Weekly audits will be done by the Operations Manager (POM) or detecting drywall repairs. Weekly audits will be done by the Operations Manager (POM) or detecting and all ceiling repacempleted in compliance with NF 8.3.1.2 *(2012 Edition). Audit results will be reviewed at the Quality Assurance Process Improve meetings x 2 months, then re-evaluanced to continue monitoring therafte 	alked in om were or drywall /2018. /2018. by the to be with ough or noted. B by of perations oper Plant esignee irs are PA 101, 1, 8.3.4.1 ment the	3/20/20

If continuation sheet 1 of 1